## Date of Inspection: 12 FIELD INSPECTION REPORT Division: Pw. p Name of the Road: Delical 20 District: Muyoffurpi Scheme/Programme: Length (km): Package No.: MAINTENANCE TOSR Status of the Project: FUTOR WA Work is a case of: Ongoing/Completed/Under Maintenance\ Road Id No.: 3/57 New Connectivity/Up gradation/ Maintenance SI. No. Parameters to be checked 1. Payement Road Junction condition Remarks b) Condition of Surfacing c) Riding Quality LS/U d) Road Camber S/U Whether free from LSIU aggregates in case of CC Pavement. defects such as visible cracks, exposed VS/U Contraction Joints provided or not (CC Pavement) f) CYes/No Compaction of flank/slope & raincuts if any g) 2. ∨Yes/Na Cross Drainage Condition of head walls in Hume pipe culverts including its painting CYes/No Condition of Abutment & Wing walls, Slab in RCC culverts b) c) Condition of railings/slab/approach for Bridges C8/SRI/U VS/SRI/U 3, Road Furniture S/SRI/U Whether sign boards/informatory/cautionary Board/km & 200m a) stones/Pavement road markings are provided and maintained 4 Compliance History Yes/No a) Status of ATR's & any others

Overall Rating

	KA
Satisfactory (S)	
Satisfactory but requires Y	6.
Unsatisfactory (U)	

(Signature)

NAME: Subjantosayeran pains

DESIGNATION: IR puru.