

# FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District : E. Champaran
Division : Chakea		Length (Km): 1.600
Name of the Road : L03 rangadwa to Kurni to la		
Scheme/Programme : MAINTENANCE		
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	'S'
b)	Condition of Surfacing	'S'
c)	Riding Quality	'S'
d)	Road Camber	'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	'S'
f)	Contraction Joints provided or not (CC Pavement)	'S'
g)	Compaction of flank/slope & raincuts if any	'U'
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	'S'
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	'U'
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	

Note :- Flank are damaged in some length (approx 150m) and painting of board are required.

NAME :

DESIGNATION :

*[Signature]*  
21.12.2020  
J.E

(Signature)