

FIELD INSPECTION REPORT

Date of Inspection: 19/11/20		District: Shikhar
Division: R.W.D. Shikhar		Length (km): 1.210 km
Name of the Road: Chakrayan Beldan to Kapas		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
S.No.		
a) Road Junction condition		
Condition of surface.		S/U
c) Riding Quality		S/U
d) Road Camber		S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f) Contraction Joints provided or not (CC Pavement)		Yes/No
g) Compaction of flank/slope & raincuts if any		Yes/No
2. Cross Drainage		
b) Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c) Condition of railings/slab/approach for Bridges		S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.	Yes/No
4. Compliance History		

Overall Rating :

Satisfactory (S)	+
Satisfactory but requires Improvement (SRI)	x
Unsatisfactory (U)	- U -

(Signature)

NAME: AMIL K

DESIGNATION: AE