GTSNY.

FIELD INSPECTION REPORT

	spection:	16/12/2020	District: Igrous'	
			Length (km): 0.600 Km	
		myyaki Bhar	van Garauni To KA	alignan
	rogramme:	MAINTENANCE	Laborative PND	Rome
Package I		•	Road Id No.: \$080410	1823
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance		
	2		Jp gradation/ Maintenance	Ha Demakronie Sport Alle
SI. No.		Parameters to	be cliecked	Remarks
1.	Pavement			in silenti. Indestrumbasi
a)	Road Junction condition			SÆ
b)	Condition of Surfacing			SAU
c)	Riding Quality			SAL
d)	Road Camber			SAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			_Yes/No
2. 2.	Cross Drain	age		
a)	Condition of head walls in Hume pipe culverts including its painting			_ S /SRI/ U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/ SRI/U
c)	Condition of railings/slab/approach for Bridges			S/ SRI/ U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			-Yes /No
4.	Compliance History			
a)	Status of ATR's & any others			NA

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Br. 11/2/20

AE, Laxmipur

(Signature)

NAME:

DESIGNATION: