


FIELD INSPECTION REPORT

Date of Inspection :- 19.12.20	District :- Khagaria
Division :- Khagaria	Length (Km) :- 2.106
Name of Road :- Fultara to Khatana	
Scheme/Programme :- PHGSY	Maintenance <input checked="" type="checkbox"/>
Package No. :-	Road ID No. :-
Status of Project :- 5th years maintenance work	Ongoing/Complete/Under Maintenance
Work is a case of :-	New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/>

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	<input checked="" type="checkbox"/> S/U
b)	Condition of Surface	<input checked="" type="checkbox"/> S/U
c)	Riding Quality	<input checked="" type="checkbox"/> S/U
d)	Road Camber	<input checked="" type="checkbox"/> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <input checked="" type="checkbox"/>
f)	Construction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No <input checked="" type="checkbox"/>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI) <input checked="" type="checkbox"/>	SRI
Unsatisfactory (U)	


 19.12.20
 J. E. / Plank
 (Signature)