

FIELD INSPECTION REPORT

| | | |
|--|--|--|
| Date of Inspection :- 19.12.20 | | District :- Khatgania |
| Division :- Khatgania | | Length (Km) :- 0.735 |
| Name of Road :- 701 to Aurah | | |
| Scheme/Programme :- PH-6134 | | Maintenance <input checked="" type="checkbox"/> |
| Package No. :- | | Road ID No. :- |
| Status of Project :- 5th year Maintenance work | | Ongoing/Complete/Under Maintenance <input checked="" type="checkbox"/> |
| Work is a case of :- | | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked | Remarks |
|-----------|--|---|
| 1. | Pavement | |
| a) | Road Junction Condition | <input checked="" type="checkbox"/> S/U |
| b) | Condition of Surface | <input checked="" type="checkbox"/> S/U |
| c) | Riding Quality | <input checked="" type="checkbox"/> S/U |
| d) | Road Camber | <input checked="" type="checkbox"/> S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | NA Yes/No <input checked="" type="checkbox"/> |
| f) | Construction Joints provided or not (CC Pavement) | NA Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No <input checked="" type="checkbox"/> |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | NA S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC Culverts | NA S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | NA S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained | <input checked="" type="checkbox"/> Yes/No |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | NA |

Overall Rating :

| | |
|--|---|
| Satisfactory (S) <input checked="" type="checkbox"/> | S |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

(Signature)