## FIELD INSPECTION REPORT

		PLEEDY HARLE	TION KISTOKY			
Date o						
Divisi						
Name	of the Road: Ho	lim Lahimi to	kodly hout			
Schen						
Package No.:		Rond Id No.:				
Status of the Project:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance				
Work is a case of:		New Connectivity/O	Remarks			
Sl. No	Sl. No. Parameters to be checked					
, 1,	Pavement	·		VS/U		
a)	Road Junction of	Road Junction condition				
b)	Condition of Surfacing			VS/U VS/U		
c)	Riding Quality		VS/U			
d)	Road Camber					
e)	Whether free aggregates in ca	Yes/No				
f)	Contraction Joir	on Joints provided or not (CC Pavement)				
		Compaction of flank/slope & raincuts if any				
2.	Cross Drainage					
- 19	Condition of hea	S/SRI/U				
a)	Condition of Ab	S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges		S/SRI/U			
c)						
3.	Road Furniture	~				
a)	Whether sign b	Yes/No				
4.	Compliance Hist					
a)	Status of ATR's &	P45		No		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 5.E

NAME:		
W 20 4 C 3 . 1 W4 C 3 .		