

# FIELD INSPECTION REPORT

Date of Inspection: - 20.12.20		District: - Kishanganj
Division: - Kishanganj-1		Length(km): 1.000KM
Name of the Road: PMGSY TO Bahadur Munzi TO19		
Scheme/Programme: GTSNY		
Package No.: N/A		Road Id No.: 21205201200
Status of the Project:		Ongoing/Completed /Under Maintenance
Work is a case of:		New Connectivity/ Up gradation / Maintenance
S1. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints Provided or not ( CC Pavement)	✓Yes/No
g)	Compaction of flank / slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory(S)	-S-
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

NAME: Radhayanjan prajapati  
Junior Engineer  
Bahadurganj-1

*[Signature]*  
20.12.20  
J.E  
R.W.D (W) Division  
Kishanganj-1