

FIELD INSPECTION REPORT

Date of Inspection: 20/12/20		District: - Kishanganj	
Division: - Kishanganj-I		Length(km): 1.300 KM	
Name of the Road: SH 63 TO BARRI TO 19			
Scheme/Programme: Q-T3NY			
Package No.: - N/A		Road Id No.: 2/20580 1848	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
S1. No	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction Condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank / slope & raincuts if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		- N/A S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		- N/A S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		N0

Overall Rating :

Satisfactory(S)	- S -
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

NAME: Radheshyam prajapati
S.E, Bahadurganj-I

20/12/20
S.E
R.W.D (W) Division
Kishanganj-1