FIELD INSPECTION REPORT

		Sahotan MAINTENA		0 150	rupo	W. K	oac	1. (GTS). K
ackage	Programme:	MAINTENA	INCE	Road Id	No.		-	
Status of the Project:		Ongoing/Con	npleted/	-				
	a case of:	New Connect	<u> </u>					
Sl. No.	TAN HILL	Parame	ters to l	e checke	d			Remarks
1.	Pavement							Automobile 1
a)	Road Junction condition							S/U
b)	Condition of Surfacing							S/UV
e)	Riding Quality							S/U.
d)	Road Camber							S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.							Yes/No
f)	Contraction Joints provided or not (CC Pavement)							Yes/No
g)	Compaction of flank/slope & raincuts if any							Yes/No
2.	Cross Draina	ige						To be the
a)	Condition of head walls in Hume pipe culverts including its painting						nting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts							S/SRI/U
c)	Condition of railings/slab/approach for Bridges							S/SRI/U
3.	Road Furniture							
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained						200m	Yes/No
4	Compliance H	listory					No.	
a) Status of ATR's & any others							Mo	
verall R	ating .	·						
	5	Satisfactory	, , ,					
	Satisfactory but requires Improvement (SRI)					RI)		
		Unsatisfacto	ory (U)					U
							4	1 Lble

SB