

FIELD INSPECTION REPORT

Date of Inspection : 19-12-2020		District: East Champaran
Division : Arera		Length (km): 1.62
Name of the Road: Dariyapur Training School se upadhyay tola		
Scheme/Programme: MAINTENANCE		MMNSY-NDB BRIC
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	U S/U
c)	Riding Quality	U S/U
d)	Road Camber	U S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	No Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	U
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Notice have been issued to contractor.

[Signature]
19.12.20
(Signature)

NAME:

DESIGNATION:

Scanned with CamScanner

Scanned by TapScanner