

FIELD INSPECTION REPORT

Date of Inspection:	20.12.2020	District:	Purnea
Division:	Bairi	Length (km):	1.115 KM
Name of the Road:	Kshikharminiya P.S. to Dinda Tola (Udharma)		
Scheme/Programme:	MAINTENANCE	MMOSSY	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
SL No.	Parameters to be checked		
1.	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	-
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	S
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

R. B. Singh

DESIGNATION:

J.E

(Signature)

R. B. Singh
20/12/2020