

FIELD INSPECTION REPORT

Date of Inspection : 19-12-20		District : East Champaran	
Division : Chukia		Length (Km): - 0.963	
Name of the Road : Rampur Kora PMGSY road to Kadhan			
Scheme/Programme : MMGSY SC			
Package No.:		Road ID No.: - 31708401387	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1,	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	
f)	Contraction Joints provided or not (CC Pavement)	Yes	
g)	Compaction of flank/slope & raincuts if any	Yes	
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	Yes	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA	
c)	Condition of railings/slab/approach for Bridges	NA	
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	Yes	
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

'S'


19/12/20 (Signature)

NAME :

DESIGNATION :