## FIELD INSPECTION REPORT

	Inspection: 21/1		District: Buxar  Length (km): 1.405 km	
Division		iknar kirni		
	the rooms.	HOLO VCCH	Vidhyalaya.	0)0.7,620
	1.09.	IAINTENANCE	MMGS & (BRICS) Road Id No.:	
Package		ngoing/Completed	/Under Maintenance	
			p gradation/ Maintenance	
Sl. No.		Parameters to	he checked	Remarks
1.	Pavement			
a)	Road Junction condition			18/1 'S'
b)	Condition of Surfacing			187U 'S'
c)	Riding Quality			USIU'S'
d)	Road Camber			VS/U 'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/Nov
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			~87SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U NE
c)	Condition of railings/slab/approach for Bridges			S/SRI/U M/
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			No.
. "				
( Iveraii	Rating ;	Satisfactory (S)		-
Overall		Satisfactory but re	equires Improvement (\$RI)	SRI
Overan				

NAME: