


## FIELD INSPECTION REPORT

<b>Date of Inspection :</b>		<b>District:</b> MADHUBANI
<b>Division :</b> JAYNAGAR		<b>Length (km):</b> 0.381 KM
<b>Name of the Road:</b> NH-104 THUDA PIPAL TAK TO MATNAJE UTTEM KAM AT UHR		
<b>Scheme/Programme:</b>		MAINTENANCE
<b>Package No.:</b>		<b>Road Id No.:</b>
<b>Status of the Project:</b>		Ongoing/Completed/Under Maintenance MMH37 (S-U)
<b>Work is a case of:</b>		New Connectivity/Up gradation/ Maintenance
<b>Sl. No.</b>	<b>Parameters to be checked</b>	<b>Remarks</b>
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

  
19-12-2020  
(Signature)

**NAME:** SUMAN KUMAR

**DESIGNATION:** ASSISTANT ENGINEER