

FIELD INSPECTION REPORT

Date of Inspection: 20/12/2020		District: Sindh
Division: RWD Sindh		Length (km): 1.50 km
Name of the Road: Siyani to Belchi Road		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
Pavement		
a)	Road Junction condition	S/B
b)	Condition of Surfacing	S/B
c)	Riding Quality	S/B
d)	Road Camber	S/B
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
Compliance History		
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	6
Satisfactory but requires Improvement (SRI)	4
Unsatisfactory (U)	1

for (Signature) *[Signature]* 20/12/20

NAME: Anil Kumar

DESIGNATION: AE