

# FIELD INSPECTION REPORT

|                                                               |                         |
|---------------------------------------------------------------|-------------------------|
| Date of Inspection: 17.12.20                                  | District: Mahayagachal  |
| Division: R.W.D. Murugheri                                    | Length (km): 1.55       |
| Name of the Road: Mahayagachal school to Mahayagachal village |                         |
| Scheme/Programme: MAINTENANCE                                 |                         |
| Package No.:                                                  | Road Id No.: 3157401267 |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                         |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                         |

| Sl. No. | Parameters to be checked                                                                                             | Remarks  |
|---------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | <b>Pavement</b>                                                                                                      |          |
| a)      | Road Junction condition                                                                                              | ✓S/U     |
| b)      | Condition of Surfacing                                                                                               | ✓S/U     |
| c)      | Riding Quality                                                                                                       | ✓S/U     |
| d)      | Road Camber                                                                                                          | ✓S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of GC Pavement.                         | ✓Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓Yes/No  |
| 2.      | <b>Cross Drainage</b>                                                                                                |          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | ✓S/SRI/U |
| 3.      | <b>Road Furniture</b>                                                                                                |          |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No  |
| 4.      | <b>Compliance History</b>                                                                                            |          |
| a)      | Status of ATR's & any others                                                                                         | NA       |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

17.12.20  
(Signature)

NAME: Santya Nagayam patra

DESIGNATION: J.E.