

FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020		District: Muja Panchayat
Division : Q.W.3 Muja Panchayat	Length (km): 1.002 Km	
Name of the Road: Gram Rambar Ashokide Panchayat Road SC Middle School Rambar	Bhivhanpur HO-1 Hotehuyeto	
Scheme/Programme: MAINTENANCE	Road Id No.: 31507401280	
Package No.:	Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of approaches for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	/

NAME: Devendra Noh

(Signature)

19/12/2020

DESIGNATION: A.E