| Date C | of Inspection 10 | FIELD INSPECTION REPOR | trict Bhoj | THE RESERVE THE PARTY OF THE PA |
|---|--|---|--------------|--|
| District | | | igth (km): | 1.20 |
| Name of the Road: Kyrnuy - Tamri Road Diangowan to Su | | | jovan to Sur | mana (Baraka |
| Scheme/Programme MAINTENANCE | | MAINTENANCE | | |
| Package No.: Road Id No.: 1045 812 | | 1040/8/20 | 19 | |
| | | Ongoing/Completeted/Under Maint | | |
| Status of the Project: | | New Connectivity/Up gradation/Maintenance | | |
| | | Parameters to be checked | | |
| SI No. | | Parameters to be enecked | | |
| 1 | Pavment | | | _8/U |
| a) | Road Junction condition | | _S/U | |
| b) | Condition of Surfacing | | ,8/U | |
| c) | Riding Quality | | _8/U | |
| d) | Road Camber : the greeks exposed aggregates | | ggregates | Yes/No |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | | | |
| | in case of CC Pavent | provided or not (CC Pavement) | | Yes/No |
|) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| g) | | Stope & famous if any | | |
| | Cross Drainage | | | S/SRI/U |
|) | Condition of head walls in Hume pipe culverts including its painting | | S/SRI/U | |
|) | Condition of Abutment & Wing walls, Slab in RCC culverts | | S/SRI/U | |
| :) | Condition of railings/slab/approach for Bridges | | | 5/5KI/U |
| 3 | Road Furniture | | | |
| 1) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | 00m d | Yes/No |
| 4 | Compliance History | | | |
| a) | Status of ATR's & any others | | | |
| | | | | |
| Overall | Rating : | Satisfactory (S) | | |
| | | Satisfactory but requires Improvement | ent (SRI) | " SRI" |
| | | Unsatisfactory (U) | | |

Name:

Astok Rumon

19/14/2020 (Signature)

3-E. Desigination