

FIELD INSPECTION REPORT

Date of Inspection : 18.11.2024	District : Panch
Division : Buxar	Length (km) : 0.450 km
Name of the Road : Link road from Barua panchayat to Dhanu Singh	
Scheme/Programme : NAIP/NSRF	
Package No. :	Road ID No. :
Status of the Project : Ongoing/Completed/Under Review	
Work is a case of : New Construction/Upgradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road surface condition	✓
b)	Condition of Surfacing	✓
c)	Binding quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as stable cracks, exposed aggregate in case of CC Pavement	✓
f)	Construction joints provided at join (CC Pavement)	Yes/No ✓
g)	Construction of Bank slope & drainage if any	✓
2.	Cross Drainage	
a)	Condition of head walls or Home pipe culverts including its painting	Satisfactory
b)	Condition of Abutment & Wing walls Slab or RCC culverts	Satisfactory
c)	Condition of railing/slab/approach for bridges	Satisfactory
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Road km & 200m survey placement road markings are provided and maintained	✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	✓ S
Satisfactory but requires Improvement (SII)	✓ SII
Unsatisfactory (U)	✓ U

Balraj Prasad Singh
Junior Engineer
NAIP

(Signature)
J.E.