

FIELD INSPECTION REPORT

| | | | |
|------------------------|--|-------------|------------|
| Date of Inspection: | 04-12-2020 | District: | Darbhanga. |
| Division: | Barbhanga - 1 | Length(Km): | |
| Name of Road: | Muzig to Ruchaul path | | |
| Scheme/Programme: | Maintenance | | |
| Package No. | | Road Id No. | |
| Status of the Project: | Ongoing/Completed/ Under Maintenance | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | |

| S No. | Parameters to be Checked | Remarks |
|-------|---|------------|
| 1 | Pavement | |
| a) | Road Junction condition | S/U |
| b) | Condition of Surfacing | S/U |
| c) | Riding Quality | S/U |
| d) | Road Camber | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | Yes/No N/A |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No |
| g) | Compaction of flank /slope & raincuts if any | Yes/No |
| 2 | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls , Slabs in RCC culverts | S/SRI/U |
| c) | Condition of railing /slabs/ approach for Bridges | S/SRI/U |
| 3 | Road Furniture | |
| a) | Whethersign boards/ informative/ cautionary Board/ Km & 200m stones/ Pavement road markings are provided and maintained | Yes/No Yes |
| 3 | Compliance History | |
| a) | Status of ATR's & any others | No |

Overall Rating:

| | |
|--|--|
| Satisfactory (S) | |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Work in progress.

SPRI
04/12/20

(Signature)

Name:

Designation: