

FIELD INSPECTION REPORT

Date of Inspection: 22/12/20 District: East Champaran
 Division: Areraj Length (km): 4.05
 Name of the Road: Bihela New P.W.D Road Via Jitwar Pur Pipra P
 Scheme Programme: MAINTENANCE Saranyan
 Package No.: Road Id No: NEA 22 000 160
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance New M/R

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes No NO
g)	Compaction of flank slope & raincuts if any	✓ Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SRI
c)	Condition of railings/slab approach for Bridges	SRI NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes No
4.	Compliance History	
a)	Status of ATR & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

—

—

NAME:

Bindu Rajak

DESIGNATION:

Executive Engineer

P.W.D.

Regional Laboratory Darbhanga

Signature
22/12/20