

FIELD INSPECTION REPORT

Date of Inspection: 22/12/20 District: East Champaran
 Division: Areraj Length (km): 1.86
 Name of the Road: Benyanyo to Bhusala
 Scheme Programme: MAINTENANCE
 Package No.: Road Id No.: 3.17831E+11
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation/ Maintenance New M/R

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU NA
b)	Condition of Surfacing	SU NA
c)	Riding Quality	SU N.A
d)	Road Camber	SU N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

daie
 22/12/20
 (Signature)

NAME:

Bindu Rajak

DESIGNATION:

Executive Engineer
 R.W.D.

Regional Laboratory Darbhanga