

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District: Malonda	
Division : B. Harskanti		Length (km): 1.8 km	
Name of the Road: B. Harskanti Vasthalligay Path to Musgachak			
Scheme/Programme: MAINTENANCE		MR-2054	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance: ☒	
Work is a case of:		New Connectivity/Up gradation/Maintenance: ☒	
Sl. No.	Parameters to be checked	Parameters	Remarks
1.	Pavement		
a)	Road Junction condition	S/U	U
b)	Condition of Surfacing	S/U	U
c)	Riding Quality	S/U	U
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NO
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)
22.12.2020

NAME: Rana Basu K. Singh
DESIGNATION: Executive Engineer

Scanned with CamScanner