## FIELD INSPECTION REPORT

| Date of Inspection: 22.12.2020 District: Nolanda   |  | 1 16                                      | 1  |                |
|--|--|---|--|----------------|
| Division: Bikerskorsift Length (km): 1.61 km   |  | 1   | Ì  |                |
| Name of the Rout: Genas Saklehupothse Bilter 4 Love via Hand Ktylomsival Po. G. Colland, Scheme/Programme: MAINTENANCE MR. 3654.  Make |  |   |  | und wike       |
| Scheme/Programme: MAINTENANCE MR-3654- May   |  |   |  | kan Tol        |
| Package No.: Road Id No.:  |  |   | 10 00 00 00 00 00 00 00 00 00 00 00 00 0 |                |
| Status of the Project: Ongoing/Completed/Under Maintenance   |  |   |  | 7              |
| Work is a case of New Connectivity/Up gradation/ Maintenance   |  |   |  | per 1 s        |
| SI. No.  | Parameters to be checked   |   |  | Pirm           |
| 1.   | Ravement   |   |  | 26.            |
| n)   | Road Junction condition  |   | S/U U                                    | 1              |
| - b)   | Condition of Surfacing   |   | S/U V                                    | -              |
| - c)   | Riding Quality   |   | S/U U                                    |                |
| d)   | Road Camber  |   | S/U S                                    |                |
| c)   | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. |   | Yes/No                                   | and the second |
| f)   | Contraction-Joints provided or not (CC Pavement)   |   | Yes/No -                                 |                |
| ( g)   | Compaction of flank/slope & raincuts if any  |   | Yes/Noya                                 | A CHARLES LINE |
| 2.   | Cross Drainage   |   |  |                |
| a) a   | Condition of head walls in Hume pipe culverts including its painting                         |   | S/SRI/U                                  | N.A            |
| b)   | Condition of Abutment & Wing walls, Slab in RCC culverts                                     |   | S/SRI/U                                  | W.A            |
| c)   | Condition of railings/slab/approach for Bridges  |   | S/SRI/U                                  | N-B            |
| 3.   | Road Furniture   |   | -5 74                                    | Sept 4 Const   |
| a)   | Whether sign boards/informatory/caution stones/Pavement road markings are provide            | nary Board/km & 200m<br>ed and maintained | Yes/No                                   |                |
| 型是   | Compliance History   |   |  |                |
| ** <b>E)</b> **  | Status of ATR's & any others   | the second of                             |  | Marie T        |

Overall Rating
Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature) 20 20

NAME: Rana Basan Ko. Singh DESIGNATION: Enecodore Engineer

Scanned with CamScanner