


FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District: Nalanda
Division : Biharchan		Length (km): 2.5 Km
Name of the Road: NH-82 Asthawan to Deehna		
Scheme/Programme: MAINTENANCE		MR-3054
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance/Completed
Work is a case of:		New Connectivity/Up gradation/ Maintenance/Other
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/ND
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No/ND
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.B.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.B.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ND
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U


22.12.2020
(Signature)

NAME: Rama Basim Kr. Singh
DESIGNATION: Executive Engineer

Scanned with CamScanner