

FIELD INSPECTION REPORT

Date of Inspection : 21-12-2020		District: Sitamarhi
Division : Sitamarhi		Length (km): 2.415 (S. 8 km)
Name of the Road: Surghahiya se Panna		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 31607908087
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Field officer reported crust 'U' But overall grading SRI

NAME: CALAN PRASAD

DESIGNATION: E.E.

Calan Prasad
(Signature)

FIELD INSPECTION REPORT

Date of Inspection : 20-12-2020		District : S. Chinnappa																																																				
Division : S. Chinnappa		Length (km) : 7.57																																																				
Name of the Road : S. Chinnappa		Scheme/Programme : MAINTENANCE																																																				
Package No. :		Road Id No. : 3164555550																																																				
Status of the Project : Ongoing/Completed/Under Maintenance																																																						
Work is a case of : New Connectivity/Up gradation/ Maintenance																																																						
<table border="1"> <thead> <tr> <th>Sl. No.</th> <th>Particulars</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>1.</td> <td>ENVIRONMENT</td> <td></td> </tr> <tr> <td>a)</td> <td>Road Junction condition</td> <td>✓</td> </tr> <tr> <td>b)</td> <td>Condition of Surfacing</td> <td>✓</td> </tr> <tr> <td>c)</td> <td>Riding Quality</td> <td>✓</td> </tr> <tr> <td>d)</td> <td>Road Camber</td> <td>✓</td> </tr> <tr> <td>e)</td> <td>Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.</td> <td>Yes/No</td> </tr> <tr> <td>f)</td> <td>Contraction Joints provided or not (CC Pavement)</td> <td>Yes/No</td> </tr> <tr> <td>g)</td> <td>Compaction of Backfills & rainouts if any</td> <td>Yes/No</td> </tr> <tr> <td>2.</td> <td>Drainage</td> <td></td> </tr> <tr> <td>a)</td> <td>Condition of head walls in storm pipe culverts including its painting</td> <td>✓</td> </tr> <tr> <td>b)</td> <td>Condition of Abutment & Wing walls, Slab in RCC culverts</td> <td>✓</td> </tr> <tr> <td>c)</td> <td>Condition of railings/slabs/approach for bridges</td> <td>✓</td> </tr> <tr> <td>3.</td> <td>Road Furniture</td> <td></td> </tr> <tr> <td>a)</td> <td>Whether sign boards/informatory/mandatory Board/Sign & other stores/Pavement road markings are provided and maintained</td> <td>Yes/No</td> </tr> <tr> <td>4.</td> <td>Compliance History</td> <td></td> </tr> <tr> <td>a)</td> <td>Status of ATR's & any others</td> <td></td> </tr> </tbody> </table>				Sl. No.	Particulars	Remarks	1.	ENVIRONMENT		a)	Road Junction condition	✓	b)	Condition of Surfacing	✓	c)	Riding Quality	✓	d)	Road Camber	✓	e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	f)	Contraction Joints provided or not (CC Pavement)	Yes/No	g)	Compaction of Backfills & rainouts if any	Yes/No	2.	Drainage		a)	Condition of head walls in storm pipe culverts including its painting	✓	b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓	c)	Condition of railings/slabs/approach for bridges	✓	3.	Road Furniture		a)	Whether sign boards/informatory/mandatory Board/Sign & other stores/Pavement road markings are provided and maintained	Yes/No	4.	Compliance History		a)	Status of ATR's & any others	
Sl. No.	Particulars	Remarks																																																				
1.	ENVIRONMENT																																																					
a)	Road Junction condition	✓																																																				
b)	Condition of Surfacing	✓																																																				
c)	Riding Quality	✓																																																				
d)	Road Camber	✓																																																				
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No																																																				
f)	Contraction Joints provided or not (CC Pavement)	Yes/No																																																				
g)	Compaction of Backfills & rainouts if any	Yes/No																																																				
2.	Drainage																																																					
a)	Condition of head walls in storm pipe culverts including its painting	✓																																																				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓																																																				
c)	Condition of railings/slabs/approach for bridges	✓																																																				
3.	Road Furniture																																																					
a)	Whether sign boards/informatory/mandatory Board/Sign & other stores/Pavement road markings are provided and maintained	Yes/No																																																				
4.	Compliance History																																																					
a)	Status of ATR's & any others																																																					

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Field officer reported that the road is badly damaged due to overflowing of water in field regularly and certain portion has been maintained by local body.

NAME: LALAN P. P. P.

DESIGNATION: E.T.

L. Chinnappa
(Signature)

FIELD INSPECTION REPORT

Date of Inspection: 20-10-2020		District: Gadag
Division: 51198001		Length (km): 4.3
Name of the Road: Dhargurur - 130th		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No: 3160490 2096
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & rainouts if any	Yes/No ✓
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

1

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME: LALAN PRASAD

DESIGNATION: E.E.

Lalan Prasad
(Signature)

FIELD INSPECTION REPORT

Date of Inspection :	20-12-2020	District:	Sitambarhi
Division :	Sitambarhi	Length (km):	5.8
Name of the Road:	Majorganj Se Bishambharpur nonkar		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	31607908091
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Field officer reported crut 'U'. But overall grading SRI.

Lalan Prasad
(Signature)

NAME: LALAN PRASAD

DESIGNATION: E.E.