

FIELD INSPECTION REPORT

Date of Inspection : 20-12-2020	District: Sitamohi
Division : Sitamohi	Length (km): 7.99
Name of the Road: Sonbary Se Panchayat PTH	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 31609908050
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

SR.No.	Parameter to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of OC Pavement.	Yes/No✓
f)	Contraction Joints provided or not (OC Pavement)	Yes/No
g)	Compaction of flank/slope & rainouts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U✓
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Field officer reported that 'U' hole length is badly damaged due to overlapping of water in flood regularly and certain portion broken maintenance activities by brick bats.

Lalan Prasad
(Signature)

NAME: LALAN PRASAD

DESIGNATION: E.E

FIELD INSPECTION REPORT

Date of Inspection : 20-12-2020	District: Sitamarhi
Division : Sitamarhi	Length (km): 7.89
Name of the Road: Sonbarsa se Rajwara path	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 31609508030
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Field officer reported crest 'U' ^{ATM} whole length is badly damaged due to overtopping of water in flood regularly and certain portion bricked maintenance activities by brick bats.

NAME:

LALAT PRASAD

DESIGNATION:

E-E

Lal Prasad
(Signature)

FIELD INSPECTION REPORT

Date of Inspection : 20-12-2020	District : Sitamohu
Division : Sitamohu	Length (km): 7.87
Name of the Roads : Sahayya se Palwara path	
Scheme/Programmes : MAINTENANCE	
Package No.:	Road Id No.: 21609508000
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Field officer reported crust 'U' ^{approx} whole length is badly damaged due to overtopping of water in flood regularly and certain portion breaches maintenance activities by brick bats.

Lalav Prasad
(Signature)

NAME: LALAV PRASAD

DESIGNATION: E-Z