

FIELD INSPECTION REPORT

Date of Inspection : 22/12/20	District: East Champaran
Division : Areraj	Length (km): 1.19
Name of the Road: Nawada Haisthan To Nawada Dakshin Tek	
Scheme/Programme: MAINTENANCE	
Package No.: M/R - MNY - 90-20	Road Id No.: 31708301028
Status of the Project: Ongoing Completed Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	New M/R

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N/A
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME:

Bindu Rajak

DESIGNATION:

Executive Engineer

R.W.D.

Regional Laboratory Darrbhanga

(Signature)
22/12/20