

FIELD INSPECTION REPORT

Date of Inspection : 22/12/2020		District: Begusarai	
Division : Begusarai		Length (km): 4.8 km	
Name of the Road: Begusari rostru madhuri dhala se bandawa			
Scheme/Programme:		MAINTENANCE old mark	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U S/U
b)	Condition of Surfacing	U S/U
c)	Riding Quality	S S/U
d)	Road Camber	B S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	+
Unsatisfactory (U)	U

Rectification work was going on.

Samir Kumar
(Signature) 22/12/2020

NAME: Samir Kumar

DESIGNATION: E.E.