

# FIELD INSPECTION REPORT

Date of Inspection :	21/12/2020	District:	Samarshitpur Begusari
Division :	B-11a	Length (km):	2.76
Name of the Road:	Bhagatpur Mansapur Road to Paharpur		
Scheme/Programme:	MAINTENANCE	old mark	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/>		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	U S/U	
b)	Condition of Surfacing	U S/U	
c)	Riding Quality	U S/U	
d)	Road Camber	U S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	<input checked="" type="checkbox"/>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	<input checked="" type="checkbox"/>
g)	Compaction of flank/slope & raincuts if any	Yes/No	<input checked="" type="checkbox"/>
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	WA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	<input checked="" type="checkbox"/>
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

Sanil Kumar  
(Signature) 21/12/2020

NAME: SAMIR KUMAR

DESIGNATION: E.F