

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District: Nalanda	
Division : Bihar		Length (km): 1.55 km	
Name of the Road: NH 82 to Mahiyani to Jambhoni			
Scheme/Programme:		MAINTENANCE MR-3054	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U S	
b)	Condition of Surfacing	✓ S/U S	
c)	Riding Quality	✓ S/U S	
d)	Road Camber	✓ S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No/✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/US/✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No/✓	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

(Signature)
22.12.2020

NAME: Rana Borsun Kr. Singh
DESIGNATION: Executive Engineer

Scanned with CamScanner