

50

old M/R

FIELD INSPECTION REPORT

Date of Inspection:	22-12-2020	District:	Bhojpur
Division:	Togdighat	Length (km):	9.75 km
Name of the Road:	Refurb of Road from S.H. 12 Gaurabani to Niradik		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.: 1040/708070		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	SU ✓	
b)	Condition of Surfacing	SU ✓	
c)	Riding Quality	SU ✓	
d)	Road Camber	SU ✓	
e)	Whether free from defects such as visible cracks, exposed aggregate in case of CC Pavement.	Yes/No ✓	
f)	Construction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Home pipe culverts including its painting	S/SRI/U ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓	
c)	Condition of railings/slab approach for Bridges	S/SRI/U ✓	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stakes/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	NIR	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	(U)

Remarks: Damaged surface almost throughout the length of the road. Deficient road furniture.

(Signature)

Rectification done or not: Not
Rectification started or not: Not
Notice issued or not: Yes