

(46)

old M/R

FIELD INSPECTION REPORT

Date of Inspection:	22-12-2020	District:	B Raipur
Division:	Tegdispur	Length (km):	2.2 km Jagdishpur
Name of the Road:	Repair of Road from NH-30 to Jagdishpur		
Scheme/Programme:	MAINTENANCE	Road Id No:	10401708075
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Remarks
SL No.	Parameters to be checked		
1.	Pavement		50 ✓
a)	Road Junction condition		✓SU
b)	Condition of Surfacing		✓SU
c)	Riding Quality		✓SU
d)	Road Camber		✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank slope & raincuts if any		Yes/No ✓
2.	Cross Drainage		
a)	Condition of head walls in Home pipe culverts including its painting		S-SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S-SRI ✓
c)	Condition of railings/slab approach for Bridges		S-SRI ✓
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		NIL

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(SRI)

Remarks: Appearance of depressions, patches and edge breakage at some places. 2 to 1.2 km stones not found. Deficient road furniture. Parapets not repaired & painted.

(Signature)

E.E

22/12/20

NAME:

Rectification done or not : Not

Rectification started or not : Yes

Notice issued or not : Yes

(N.A. ISHAAT)