## FIELD INSPECTION REPORT

Date	of Inspection: 22.12.2020 District: Copologic	
Division: Gobalgany-1. Length (km): 2.30 km.		20 km.
The Visit	of the Road: 13 hopfabur to Nechua Jala	1 four
Schem	ne/Programme: MAINTENANCE	
Packa	age No.: Road Id No.:	in an
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		CONTRACTOR VOLE SERVICES CONTRACTOR
SI. No	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U /
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, e aggregates in case of CC Pavement.	exposed Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No 7
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its p	ainting S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/J
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	The second second

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	11.
	M. A.

Rakesh Raujan Pandey. Exembre Engineer. NAME:

(Signature)

DESIGNATION: