

FIELD INSPECTION REPORT

Date of Inspection : 21/12/2020	District: Sonapatpur Bazar
Division : Balis	Length (km): 1.6 km
Name of the Road: Balis Parihar to Pratappur	
Scheme/Programme: MAINTENANCE	old mark
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: New Connectivity/Up gradation/ Maintenance	✓

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U S/U
b)	Condition of Surfacing	U S/U
c)	Riding Quality	U S/U
d)	Road Camber	U S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRLU ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRLU
c)	Condition of railings/slab/approach for Bridges	S/SRLU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

Sonil Kumar
(Signature) 21/12/2020

NAME: SAMIR KUMAR

DESIGNATION: E.F