

FIELD INSPECTION REPORT

Date of Inspection :	21/12/2020	District:	Banswari Bazar
Division :	Balia	Length (km):	1.15
Name of the Road:	NH-31 to Kurha Dhala to Sahabpur Kamel station		
Scheme/Programme:	MAINTENANCE	old Maint.	in Chaudhri Road
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ☒		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ☒		

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U S/U
b)	Condition of Surfacing	U S/U
c)	Riding Quality	U S/U
d)	Road Camber	U S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

Samir Kumar
(Signature) 21/12/2020

NAME: SAMIR KUMAR

DESIGNATION: F.E