

FIELD INSPECTION REPORT

Date of Inspection : 22/12/2020		District: Jehanabad.	
Division : R.N.D.W. Div. Jehanabad		Length (km): 1.10 Km.	
Name of the Road: Kasona-NH10 to Rasona kagha.			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Ongoing/Completed/Under Maintenance	
Status of the Project:		New Connectivity/Up gradation/ Maintenance	
Work is a case of:		✓	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		✓S/U
a)	Road Junction condition		S/U ✓
b)	Condition of Surfacing		S/U ✓
c)	Riding Quality		S/U ✓
d)	Road Camber		NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		NA
f)	Contraction Joints provided or not (CC Pavement)		NA
g)	Compaction of flank/slope & raincuts if any		✓Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SR/✓U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/✓U NA
c)	Condition of railings/slab/approach for Bridges		S/SR/✓U NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓cs/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)