

FIELD INSPECTION REPORT

Date of Inspection : 22/12/2020		District: Sehnaabad	
Division : R-1 D.W. Dev. Sehnaabad		Length (km): 2.30 KM	
Name of the Road: Babhna ghaku talabad Shahpur Rec. Dr. Bhabh pur			
Scheme/Programme: MAINTENANCE		Shahpur Rec. Dr. Bhabh pur	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is in case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			✓ S/U
a) Road Junction condition			✓ S/U
b) Condition of Surfacing			✓ S/U
c) Riding Quality			✓ S/U
d) Road Camber			✓ S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f) Contraction Joints provided or not (CC Pavement)			Yes/No
g) Compaction of flank/slope & raincuts if any			Yes/No
2. Cross Drainage			
a) Condition of head walls in Hume pipe culverts including its painting			S/S/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts			S/S/R/U
c) Condition of railings/slab/approach for Bridges			S/S/R/U
3. Road Furniture			
a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			✓ Yes/No
4. Compliance History			
b) Status of ATR's & any others			

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	U

NAME:

22/12/2020
E-E
R. Lab
K. Parbat