

(48)

old MLR

FIELD INSPECTION REPORT

Date of Inspection : 22-12-2020		District: Bhojpur
Division :		Length (km): 7.0 km
Name of the Road: SH-12 Gopabandhu to HH-30 Hasegama via Madhwa Sahasr		Saharwan Road (part-2)
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.: 10901708055	
Status of the Project:	Ongoing/Completed/Under Maintenance <u>under maintenance</u>	
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>Maintenance</u>	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

- Satisfactory (S)
- Satisfactory but requires Improvement (SRI)
- Unsatisfactory (U)

Remarks: Appearance of patches, edge-breakage (not throughout), Exposed aggregates in CC pavement.

Rectification done or not : Not

Rectification started or not : NO

Notice issued or not — Yes

(Signature) EG
22/12/20
EG
(N-A ISHRA)