## FIELD INSPECTION REPORT

Date of Inspection: 221(2)2020 District: Gaya			
Division: Imamgan Length (km): 2-20 km.			g pilifik gazak unin igir kada diminin peraktik quadan gili di 1 A. Hebil bahir kalan salaman g gazak naga kapanan menganan palambah didi pengadan ini di selah di 1 Malada dan pel
Name of the Road: Goti hand to kabisa.			
Scheme/Programme: MAINTENANCE New			
Package No.: Road Id No.:			
Status of the Project: Ongoing/Completed/Under Maintenance  Work is a case of: New Connectivity/Up gradation/ Maintenance			
			Rémarks
Sl. No.			
1	Payement	and the second s	-
a)	Road Junction condition	at the same of the	S/IJ
- b)	Condition of Surfacing	a col	SAU
c)	Riding Quality	, P	∕\$/U
d)	Road Camber		/S/U
e)	Whether free from defects such as visible cracks, exposed nayes nearest aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		NAYes/No
g)	Compaction of flank/slope & raincuts if any Elw billing 2 Yes/No		
2.	Cross Drainage		
-a)	Condition of head walls in Hume pipe cult erts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		MAS SRITE
c)	Condition of railings/slab/approach for Bridges  NAS/SRI/U		NA S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		
Overall Rating : (S)			and the same of th
Satistactory (5)			A STATE OF THE PERSON NAMED IN THE PERSON NAMED IN
Satisfactory but requires Improvement (SRI)			

(Signature)

DESIGNATION: E.E.