

# FIELD INSPECTION REPORT

|                        |                                            |              |          |
|------------------------|--------------------------------------------|--------------|----------|
| Date of Inspection :   | 22/12/2020                                 | District:    | Gaya     |
| Division :             | Imamganj                                   | Length (km): | 2.620 km |
| Name of the Road:      | Banke Bazar to Jura Bechu Bagaha           |              |          |
| Scheme/Programme:      | MAINTENANCE New                            |              |          |
| Package No.:           |                                            | Road Id No.: |          |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |          |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |          |

| Sl. No. | Parameters to be checked                                                                                             | Remarks              |
|---------|----------------------------------------------------------------------------------------------------------------------|----------------------|
| 1.      | <b>Pavement</b>                                                                                                      |                      |
| a)      | Road Junction condition                                                                                              | ✓ S/U                |
| b)      | Condition of Surfacing                                                                                               | work in progress S/U |
| c)      | Riding Quality                                                                                                       | S/U                  |
| d)      | Road Camber                                                                                                          | S/U                  |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | NA Yes/No            |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | NA Yes/No            |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No             |
| 2.      | <b>Cross Drainage</b>                                                                                                |                      |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | NA SRI               |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | NA SRI/U             |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | NA SRI/U             |
| 3.      | <b>Road Furniture</b>                                                                                                |                      |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No             |
| 4.      | <b>Compliance History</b>                                                                                            |                      |
| a)      | Status of ATR's & any others                                                                                         | NO                   |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

NAME:

Sri Kant Prasad

DESIGNATION:

EE.

(Signature)

37  
22/12/2020