

BLOCK-KAKO

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District: Jehanabad.
Division : Jehanabad.		Length (km): 0.500 Km.
Name of the Road: NH10 KAKOTO KASTURWA SCHOOL.		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: <u>Ongoing/Completed/Under Maintenance</u>		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	on-going Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others.	

Overall Rating :

Work in Progress

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	/