

FIELD INSPECTION REPORT

Hulabaganj

Date of Inspection : 21/12/2020		District: Jalandhar
Division : Jalandhar		Length (km): 2.00 K.m.
Name of the Road: Katakuli to Rustampur		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: ☒ Ongoing/Completed/Under Maintenance		(New maintenance policy 2018)
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.		
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	ON-Going Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	ON-Going Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	/

(Signature)

21/12/20
E-E
R. Lab
Gulzar
Patel