

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020 District: KAIMUR
 Division: BHABHUA Length (km): 6
 Name of the Road: BHABHUA SILK THE UJARI
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: 10301502005
 Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a.	Road Junction condition	ST
b.	Condition of Surfacing	ST
c.	Riding Quality	ST
d.	Road Camber	ST
e.	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f.	Contraction Joints provided or not (CC Pavement)	Yes/No
g.	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a.	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b.	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U
c.	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a.	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a.	Status of ATR's & any others	

N.A

N.A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Post Patch work in Progress,

Arum Kumar Mahato
 (Signature) 18.12.20

NAME: Er. Arun Kumar Mahato