FIELD INSPECTION REPORT

	and the same property and the same	The state of the s	
Date of	Inspection: 2	Illywoo District:	
DIVISIO	DIVISION: 10 Kari		annoniu pinille pë bil ding etër mi vid e sërrë prave njudise pë 47 A, 1-647 r da spanise m
me wat hora pakas to kill (to)			
MAINTENANCE NO.			
Package No.:			enforceren, men e dat bade selle une med derje blift sellede medition verset selle inches serve sed
Status of the Project: Ongoing/Completed/Under Maintenance		ng di distribut di manadanang pingga par nad ng binggan na mada ng binggan na sa balanggan di sa babangga	
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be elecked		Remarks
1	Pavement		
a)	Road Junction condition		SIL
b)	Condition of Surfacing WBMGTH Provided.		SAJ
c)	Riding Quality		-S/U
d)	Road Camber		₩87Ū
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		NA Yes/No
g)	Compaction of flank/slope & raincuts if any Yes/N		Yes/No
2.	Cross Drainage		
- a)	Condition of head walls in Hume pipe culverts including its painting NASSRIA		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts NA S. SRI/U		
c)	Condition of railings/slab/approach for Bridges UAS/SRL/U		
3.	Road Furniture		
a) .	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		No.
work in progress.			
		Satisfactory (S)	5
		Satisfactory but requires Improvement (SRI)	
		Unsatisfactory (U)	

NAME: Sin want proved.

DESIGNATION: E.E.