

FIELD INSPECTION REPORT

| Date of Inspection : 20.12.2020 | | District : Bhagalpur |
|---|--|--------------------------|
| Division : Bhagalpur | | Length (km) : 1.3 |
| Name of Road : Repair of road from Datwat to Aliganj via Shalepur | | |
| Scheme/Programme : OLD MR | | |
| Package No. : | | Road Id No.: 20703208227 |
| Status of the Project : Under Maintenance | | |
| Work is a case of : Maintenance | | |
| SI. No. | Parameters to be checked | Remarks |
| 1 | Pavement | |
| a) | Road Junction condition | U |
| b) | Condition of Surfacing | U |
| c) | Riding Quality | U |
| d) | Road Camber | S |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | No. |
| f) | Contraction Joints provided or not (CC Pavement) | Yes |
| g) | Compaction of flank/slope & raincuts if any | No. |
| 2 | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | NA |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | NA |
| c) | Condition of railings/slab/approach for Bridges | NA |
| 3 | Road Furniture | |
| a) | Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained | No. |
| 4 | Compliance History | |
| a) | Status of ATR's & any others : Riding quality is very boor. | No. |

Overall Rating :

| | |
|---|---|
| Satisfactory (S) | U |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER

(Signature)

[Handwritten Signature]
20.12.2020