

FIELD INSPECTION REPORT

Date of Inspection :		23/12/2020	District :	Mungoo
Division :	Kharagpur Tqoc Pur		Length (Km) :	1.192
Name of the Road :		L-38 Porja to Lamer		
Scheme/Programme :		MAINTENANCE ✓		
Package No. :	BR-22R-098	Road Id No. :	N/A	
Status of the Project :		Ongoing/Completed/Under Maintenance ✓		
Work is a case of :		New Connectivity/Up gradation/Maintenance ✓		
Sl. No.	Parameters to be checked			Remarks
1	Pavement			
a)	Road Junction condition	S/U	S	
b)	Condition of Surfacing	S/U	S	
c)	Riding Quality	S/U	S	
d)	Road Camber	S/U	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes	
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes	
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	} N/A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes	
4	Compliance History			
a)	Status of ATR's & any others	NO		


Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME :

DESIGNATION :

shailendra
J.E


(Signature)