


FIELD INSPECTION REPORT

Date of Inspection :	23-12-2020	District :	Munger
Division :	Khagaria - Togaeri	Length (Km) :	
Name of the Road :	Togaeri - Khagaria Road To Maheshpur to Horizon Tola Maheshpur		
Scheme/Programme :	MAINTENANCE ✓		
Package No. :	RR-22R-143	Road Id No. :	N/A
Status of the Project :	Ongoing/Completed/Under Maintenance ✓		
Work is a case of :	New Connectivity/Up gradation/Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	} N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NO
4	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Shaikudhan K
DESIGNATION: J.E


(Signature)