

FIELD INSPECTION REPORT

Date of Inspection: 22-12-2020		District: Sheikhpura	
Division: Sheikhpura		Length (km): 1.150 km	
The Road: Barendaban ke Dakshin Paschim Se Lakshminpura			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	✓ S/U	BT Surface Boker
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & taluqs if any	100% ✓	
2.	Cross Drainage		Gorries in plank
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
3.	Road Furniture		All Board are in dirty condition. No logs & Road furniture 20m stone
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.	Yes/No	
4.	Compliance History		
Status of ATR's & any others			

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SP)	✓
Unsatisfactory (U)	

(Signature) 22-12-2020

NAME: PANKAJ KUMAR
DESIGNATION: JE, ARIYARI